

Notice

SANYO

CORRECTION
 SERVICE FLASH

PRODUCTION CHANGE
 ADD INFORMATION

FILE NO.

Please add this notice to the Service Manual listed below.

REVISION 3

Category: **COLORTELEVISION**

Date: **September / 10 / 2007**

Model: **DP42647**

Effective from : Chassis No. **P42647-03** ←

Destination: **U.S.A. / CANADA** REF. No. **SM780144-03**

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. **If the Service Manual Chassis No. does not match the unit's**, additional Service Literature is required. This chassis is similar to Chassis No. P42647-00. Only the **difference** Service Information is given in this manual. For detailed Service Information, refer to the **Original Service Manual** and **Notices** for Chassis No. P42647-00 used in Model DP42647 (SM780144).

Servicing should be performed by only trained and qualified service personnel.

1. IN THE CHASSIS ELECTRICAL PARTS LIST MAIN PC BOARD AND MISCELLANEOUS

The reason for change.

A : Misprint B : Quality Reliability C : Standardization
D : Design E : Add as a possible sub F : Schematic location change
G : Purchasing Request

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchangeability	Reason
Page 9 Chassis Electrical Parts List	C681	Old	CK1H104ZLZFNG	CERAMIC 0.1U Z 50V	1	NO	D
		New	N/A	NOT USED	0	NO	
Page 11 Chassis Electrical Parts List	C5722	Old	CK1H104ZLZFNG	CERAMIC 0.1U Z 50V	1	NO	D
		New	N/A	NOT USED	0	NO	
	C5724	Old	CK1H104ZLZFNG	CERAMIC 0.1U Z 50V	1	NO	D
		New	N/A	NOT USED	0	NO	
	C5725	Old	CK1H104ZLZFNG	CERAMIC 0.1U Z 50V	1	NO	D
		New	N/A	NOT USED	0	NO	

1. IN THE CHASSIS ELECTRICAL PARTS LIST MAIN PC BOARD AND MISCELLANEOUS

The reason for change.

A : Misprint	B : Quality Reliability	C : Standardization
D : Design	E : Add as a possible sub	F : Schematic location change
G : Purchasing Request		

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchangeability	Reason
Page 11 Chassis Electrical Parts List	C5726	Old	CK1H104ZLZFNG	CERAMIC 0.1U Z 50V	1	NO	D
		New	N/A	NOT USED	0	NO	
	C5727	Old	CK1H104ZLZFNG	CERAMIC 0.1U Z 50V	1	NO	D
		New	N/A	NOT USED	0	NO	
	C5728	Old	CK1H104ZLZFNG	CERAMIC 0.1U Z 50V	1	NO	D
		New	N/A	NOT USED	0	NO	
	C5729	Old	CK1H104ZLZFNG	CERAMIC 0.1U Z 50V	1	NO	D
		New	N/A	NOT USED	0	NO	
Page 13 Chassis Electrical Parts List	IC5700	Old	QXXAVC524---M	1C EDD1216AATA-6B-E	1	NO	D
		New	QXXAVC926---M	1C EDD2516AETA-5B-E	1	NO	
	IC5720	Old	QXXAVC524---M	1C EDD1216AATA-6B-E	1	NO	D
		New	N/A	NOT USED	0	NO	
Page 18 Chassis Electrical Parts List	RB5578	Old	1AV4R1D31504G	R-NETWORK 15X4 1/32W	1	NO	D
		New	N/A	NOT USED	0	NO	
	RB5579	Old	1AV4R1D31504G	R-NETWORK 15X4 1/32W	1	NO	D
		New	N/A	NOT USED	0	NO	
	RB5580	Old	1AV4R1D31504G	R-NETWORK 15X4 1/32W	1	NO	D
		New	N/A	NOT USED	0	NO	
	RB5581	Old	1AV4R1D31504G	R-NETWORK 15X4 1/32W	1	NO	D
		New	N/A	NOT USED	0	NO	
Page 20 Chassis Electrical Parts List	R5578	Old	RGF15R0JTCANL	MT-GLAZE 15 JA 1/10W	1	NO	D
		New	N/A	NOT USED	0	NO	
	R5579	Old	RGF15R0JTCANL	MT-GLAZE 15 JA 1/10W	1	NO	D
		New	N/A	NOT USED	0	NO	
	R5580	Old	RGF15R0JTCANL	MT-GLAZE 15 JA 1/10W	1	NO	D
		New	N/A	NOT USED	0	NO	

1. IN THE CHASSIS ELECTRICAL PARTS LIST MAIN PC BOARD AND MISCELLANEOUS

The reason for change.

A : Misprint	B : Quality Reliability	C : Standardization
D : Design	E : Add as a possible sub	F : Schematic location change
G : Purchasing Request		

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchange-ability	Reason
Page 21 Chassis Electrical Parts List	R5581	Old	RGF15R0JTCANL	MT-GLAZE 15 JA 1/10W	1	NO	D
		New	N/A	NOT USED	0	NO	
	R6088	Old	RGFR000ZTCANL	MT-GLAZE 0.000 ZA 1/10W	1	NO	D
		New	RGF1200FTCANL	MT-GLAZE 120 FA 1/10W	1	NO	
Page 23 Chassis Electrical Parts List	▲U901	Old	1AV4U20C10000	UNIT, INVERTER-POWER	1	NO	D
		New	1AV4U20C17400	UNIT, INVERTER-POWER	1	NO	

For parts or service contact

Sanyo Manufacturing Corporation
PO. Box 2000
3333 Sanyo Road
Forrest City, Arkansas 72335-2000